



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
(801) 538-5340 telephone
(801) 359-3940 fax
(801) 538-7223 TTY
www.nr.utah.gov

Michael O. Leavitt
Governor
Robert L. Morgan
Executive Director
Lowell P. Braxton
Division Director

September 10, 2002

CERTIFIED RETURN RECEIPT
7099 3400 0016 8895 6559

Mr. Duane Crutchfield
Ash Grove Cement Company
P.O. Box 51
Nephi, Utah 84648

Re: Five-Year Review of Reclamation Surety Estimate, Ash Grove Cement Company,
Nielson S.S. Quarry, M/023/012, Juab County, Utah

Dear Mr. Crutchfield:

The Division performs periodic reviews of reclamation surety estimates to verify their accuracy. We make adjustments for escalation and any site modifications that may require a change in the amount of reclamation surety presently being held for the site. Division policy requires that reclamation surety estimates being held by the Minerals Reclamation Program include a five year escalation component. The surety estimates are to be reevaluated every five years. A number of these five-year surety assessments are overdue because of more pressing program priorities.


Our records indicate that the reclamation surety estimate for Ash Grove Cement Company's Nielson S.S. Quarry is due for review this year. To assist us in our review of this cost estimate, we request an updated map of your mine site showing current surface facilities and all mining related disturbances. Please provide the updated map at a scale of not less than 1 inch = 500 feet, which includes: buildings, stationary mining/processing equipment, roads, utilities, power lines, drainage structures (i.e. berms, culverts, etc.), topsoil, ore and product storage areas, overburden/waste dumps, tailings or processed waste facilities, solid and liquid wastes, and wastewater discharge treatment and containment facilities, etc. This map should include all areas which have been affected by this operation to date. Please ignore items listed above which do not apply to your site.

Page 2
Duane Crutchfield
M/023/012
September 10, 2002

If any reclamation has been completed on the site since the last surety estimate review, please provide a separate map of the same scale as the site facilities and disturbed area map, clearly identifying these reclaimed areas, the acreage affected, and the date of the reclamation. Please cross-hatch or shade the areas to identify the reclamation treatments (i.e. ripping, regrading, mulching, seeding, etc.) which have been applied.

Please provide this information within the next 60 days or no later than November 12, 2002. If you are unable to provide this information in this time frame, please contact the Division with justification for requesting additional time. Thank you for providing this information to assist us in our surety estimate review. If you have any questions concerning this letter, please contact Doug Jensen at (801) 538-5382.

Sincerely,



D. Wayne Hedberg
Permit Supervisor
Minerals Regulatory Program

jb

cc: Ed Ginouves, BLM, Cedar City FO
P:\GROUPS\MINERALS\WP\M023-Juab\M0230012 Nielson SS Quarry\Final\M23-12-bnd-rvw.doc